

High Powered PEMF Semi Kit Parts List

Completely populated motherboard/PCB

100 Watt 100 ohm heat sink resistor

1500 ufd Electrolytic 250 Volt capacitor with 7/16" extra mounting screws (most expensive item)

Two 6 position rotary switches with 1K resistors mounted, included with PCB

Two rotary switch knobs, included with PCB

Two toggle switches for speed and time control, included with PCB

110 AC to 12 volt power supply with labeled pigtails

15 Amp on/off switch

12 volt cooling fan with grill

Push button pigtail software controlled function switch, included with PCB

Pigtail status with mounted current limit resistor LED (Resistor now on the Bd)

Case mounted fuse holder and 8 amp slow blow fuse.

Extra fuses (usually 10 amp slow blow)

6 foot power cord

Blank 6 x 5 x 3 Project Box

2 grommets (Used for power cord input & output)

2 Resistor Standoffs

3 grill covers 2" for venting holes.

2 nylon PCB standoff washers or 2 nylon nuts (better)

12 mounting screws, washers and nuts 4/40 for grill covers

6 power supply, 100 watt resistor PCB mounting screws and nuts 4/40, tiny for power supply

2 tie wraps

4 Rubber Mounting Feet